## 熱風循環式コンベア炉(中温)RBC型 Air Circulation Type Ovens with Conveyor (for Medium

RBC型連続炉は、100~450°Cの温度範囲のテンパー、アニーリング、 各種乾燥、ベーキング、熱硬化ガラスの焼成、ハンダ付などの低温熱処理に 使用するコンベアタイプ連続加熱装置です。


シーズヒーターの使用と、強力な循環ファンにより、精密な温度分布が とれます。

コンベアの上にワークを連続的にならべるだけで多量の熱処理が 自動的にできます。

## **Heating) Model RBC**

The Model RBC ovens are suitable for tempering, annealing, drying, baking, heat curing, and soldering under medium temperature of 100°C-500°C.

Pipe heaters and powerful mixing fans attached to the oven create excellent temperature distribution. Just place the works continuously on the conveyor belt, then they are automatically heat-treated.



コンベア駆動部

## [特性]

- ① 進行方向で1~5点のゾーン制御を行い、また1~5基の撹拌ファンを取り付け 熱風循環をして、温度の均一化をはかっています。
- ② スピードコントローラーの調整により、加熱時間(炉内通過時間)を2分~70分に 可変できます。
- ③ 計算された表面負荷 (W/cm²) 容量のシーズヒーター装着で寿命は長く、 また交換も簡単です。
- ④ ステンレスメッシュベルト方式ですので、搬送面がフラットであり、ほとんどのワークを 自由に並べることができ、重量物の搬送にも適しています。
- ⑤ 無酸化加熱方式 (H2, N2) もあります。(BCE型)

- 1. Temperature is controlled independently in 1-5 zones divided on the conveying process, and its distribution is equalized by a mixing fan attached to each zone.
- 2. You can control the heating time (passing time of a work through the oven) between 2 and 70 minutes by adjusting the speed controller.
- 3. The pipe heaters with designed surface load (W/cm<sup>2</sup>) capacity have long service life and are of easy replacement.
- 4. The conveyor belt is made of stainless steel mesh. It is flat and strong enough to bear works of miscellaneous shapes and heavy weight.